

Annex B2

RFQ/UNHCR/JOR/2026/3620

Spare parts list for X-ray machines and Walk Through

1. X-ray machine Spare Part:			
1	X-ray tube	1	Unit
2	Filters	1	Unit
3	Collimators	1	Unit
4	Cables	1	Unit
5	Connectors.	1	Unit
6	Computer	1	Unit
7	Monitor	1	unit
8	Detectors	1	Unit
9	Interlock Switch	1	Unit
10	Power Distribution Unit	1	Unit
11	UPS	1	Unit
12	Emergency Stop Switch	1	Unit
13	Conveyor Motor	1	Unit
14	Conveyor Belt	1	Unit
15	Motor Drive	1	Unit
16	Molex Connector	1	Unit
17	Photo Sensor	1	Unit
18	X-Ray Source	1	Unit
19	Keypad	1	Unit

20	Cooling systems	1	Unit
21	Control Board for X-ray source	1	Unit
2. Walkthrough spare parts:			
1	Panel A	5	Unit
2	Panel B	5	Unit
3	controller -gray	5	Unit
4	PCB Assbly, spare light Bar	5	Unit
5	PCB ASSY spare	5	Unit
6	Power supply module with vents	5	Unit
7	Detection unit	5	Unit
8	Crosspiece 30	5	Unit
9	Boot panel	5	Unit
10	Spare Light bar controller (Grey)	5	Unit
11	Cable assembly A det unit -short	5	Unit
12	Cable assembly A det unit -long	5	Unit
13	Power cord	5	Unit
14	Switch Assembly keylock	5	Unit
15	Extrusion (vinyl)	5	Unit

- Spare parts prices should include installation and wiring if required.
- Suppliers can price any additional spare parts not mentioned in this.